

| <u>Initial</u> | <u>Number Series</u> | <u>Model</u> | <u>Builder</u> | <u>Date</u> |
|-----------------------|-----------------------------|---------------------|-----------------------|--------------------|
| CN | 102-103 | E9A | EMD | 1949-1956 |
| CN | 104-106 | F40PHR | EMD | 1977-1978 |
| CN | 200-263 | YBU | GMD | R1980-1990 |
| CN | 268 | YBU-M | CN | 1964 |
| CN | 273-281 | YBU | GMD | R1993 |
| CN | 500-526 | HBU | GMD | R1978-1980 |
| CN | 1400-1444 | GMD-1 | GMD | R1988-1989 |
| CN | 1650, 1652, 1653 | SD38-2 | GMD | 1975 |
| CN | 2000-2041 | C40-8 | GE | 1989-1990 |
| CN | 2098,2099 | C40-8W | GE | 1992 |
| CN | 2100-2134 | C40-8 | GE | 1991 |
| CN | 2135-2199 | C40-8W | GE | 1992 |
| CN | 2200-2205 | C44-9W | GE | 2004 |
| CN | 2220-2344 | ES44DC | GE | 2006-2010 |
| CN | 2400-2454 | C40-8M | GE | 1990-1992 |
| CN | 2500-2696 | C44-9W | GE | 1994-2004 |
| CN | 2727 | C44-9W | GE | 2005 |
| CN | 2800-2924 | ES44AC | GE | 2012-2014 |
| CN | 2925-2950 | ES44AC (T4C) | GE | 2015 |
| CN | 2951-2975 | ES44AC | GE | 2015 |
| CN | 2976-2999 | ES44AC (T4C) | GE | 2016-2017 |
| CN | 3000-3242 | ET44AC | GE | 2015-2016 |
| CN | 3800-3805 | ES44AC (T4C) | GE | 2017 |
| CN | 4018, 4028 | GP9-RM | GMD | R 1982-1984 |
| CN | 4100-4141 | GP9-RM | GMD | R1984-1991 |
| CN | 4700-4810 | GP38-2 | GMD | 1972-1974 |
| CN | 5242-5386 | SD40-2 | GMD | 1973-1980 |
| CN | 5400-5489 | SD60 | GMD | 1986 |
| CN | 5600-5625 | SD70I | GMD | 1995 |
| CN | 5626-5800 | SD75I | GMD | 1996-1999 |
| CN | 6000-6028 | SD40-3Q | GMD | R1992-1993 |
| CN | 7000-7083 | GP9-RM | GMD | R1985-1993 |
| CN | 7200-7280 | GP9-RM | GMD | R1985-1994 |
| CN | 7304, 7311 | SW1200RB | GMD | R1987 |
| CN | 7500-7532 | GP38-2 | GMD | 1973 |
| CN | 8000-8024 | SD70M-2 | EMD | 2005-2006 |
| CN | 8100-8103 | SD70ACe | EMD | 2013 |
| CN | 8800-8964 | SD70M-2 | EMD | 2007-2011 |
| CN | 9402-9626 | GP40-2L | GMD | 1974-1975 |
| CN | 9639-9677 | GP40-2 | GMD | 1974-1976 |
| BCOL | 4601-4626 | C40-8M | GE | 1990-1993 |
| BCOL | 4641-4654 | C44-9W | GE | 1995 |
| BLE | 862-868 | SD38AC | EMD | 1967-1971 |
| BLE | 878 | SD38-2 | EMD | 1973 |

| | | | | |
|------|-----------------|---------|--------|-------------|
| BLE | 900-910 | SD40-3 | EMD | R 1999-2000 |
| DMIR | 211, 212, 215 | SD38-2 | EMD | 1975-1976 |
| DMIR | 400, 402-409 | SD40-3 | EMD | R 1996 |
| EJE | 656-675 | SD38-3 | EMD | 1973-1975 |
| EJE | 703 | GP38-2 | EMD | 1972 |
| GTW | 4610-4633 | GP9-RB | EMD | R 1989-1993 |
| GTW | 4900-4934 | GP38-2 | EMD | 1972 |
| GTW | 5812-5861 | GP38-2 | EMD | 1977-1980 |
| GTW | 5930-5937 | SD40-2 | EMD | 1975 |
| GTW | 5938-5955 | SD40-3 | GMD | R 1999 |
| GTW | 6221-6228 | GP38-2 | EMD | 1978 |
| GTW | 6401 | GP40 | EMD | 1968 |
| GTW | 6420, 6425 | GP40-2 | EMD | 1973-1979 |
| IC | 1000-1039 | SD70 | EMD | 1996-1999 |
| IC | 1200-1204 | SW7RM | EMD/IC | R 2006-2007 |
| IC | 1492-1506 | SW14 | EMD | R 1978-1982 |
| IC | 2455-2466 | C40-8W | GE | 1994 |
| IC | 2697-2726 | C44-9W | GE | 2004 |
| IC | 3101-3140 | GP40-2R | EMD | R 1987-1991 |
| IC | 6100, 6200-6204 | SD40-3 | EMD | R1997-1998 |
| IC | 6250-6264 | SD40-3 | EMD | R 1998-2000 |
| IC | 9560-9639 | GP38-2 | EMD | 1972 |
| WC | 1552-1569 | SW1500 | EMD | R 2001-2002 |
| WC | 1558-1565 | SW1500 | EMD | 1968-1971 |
| WC | 1570, 1571 | SW1500 | EMD | R 2001-2002 |
| WC | 2001-2006 | GP38-2 | GMD | 1981 |
| WC | 3018 | GP40 | EMD | 1970 |
| WC | 3026, 3027 | GP40-2R | EMD | R 1994 |